



Bulkhead Push-On SMA Male to SMA Female Bulkhead Adapter

	Connector 1	Push-On SMA Male
	Impedance 1	50 Ohms
	Connector 2	SMA Female
	Impedance 2	50 Ohms
		0\$
	Mount Method	Bulkhead

0F06F0W

0F06F0W

0DH

0\$ 0DH

Bulkhead Push-On SMA Male to SMA Female Bulkhead Adapter ♂



